

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the unloading pad for the Adams Oil and Gas Enhanced Recovery Injection well 34-163-20318. Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This Photo shows the side of the facility pump house. All injection equipment has been removed.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This Photo shows the inside of the facility pump house.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the 34-163-20318 Enhanced Recovery Injection Well. Note the injection tubing is not equipped with a master valve. The annulus has zero pressure. The well is not connected to injection lines or equipment.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the state issued 1000 psi gauge installed on the annulus with all valves open. Annulus has zero pressure.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows another view of the state issued 1000 psi gauge installed on the annulus with all valves open. Annulus has zero pressure.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the containment dike wall. Note the aquatic vegetation in the containment dike.

Photo taken on 6-10-15 By ODNR/DOGGM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the Containment dike with the two 210 barrel tanks. The dike is full of water and aquatic vegetation.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.