

API Well No.  
**34087204240000**

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER\_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1} 7** No. **7** WH\_LAT: **38.636890** WH\_LONG: **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: \_\_\_\_\_ Phone \_\_\_\_\_

Address: \_\_\_\_\_

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification \_\_\_\_\_ Contact **JON SCOTT**

Inspection Comments:

**Compliance Notice # 1567619883 follow up inspection. The injection tubing is leaking brine onto the ground. Standing water at the scald area was tested with a High Range Quantab = max out over 6000 ppm Cl. The scald area is 5 feet by 4 feet.**

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSUR  Vac FLOWMETER  Vac

HAULERNO: \_\_\_\_\_ LISCENSE\_NUM \_\_\_\_\_

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: **7/20/2020**

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued: **9/4/2019**

Required action to be completed by: **9/9/2019**

Reviewed by: \_\_\_\_\_

Extended action due: \_\_\_\_\_

Forward to: \_\_\_\_\_

Required action completed: \_\_\_\_\_

Duration: 1.1 hrs Section/Name \_\_\_\_\_