

API Well No.  
**34087204240000**

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER\_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1} 7** No. **7** WH\_LAT: **38.636890** WH\_LONG **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: \_\_\_\_\_ Phone \_\_\_\_\_

Address: \_\_\_\_\_

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification \_\_\_\_\_

Contact **JON SCOTT**

Inspection Comments:

**Compliance Notice # 1567619883 follow up inspection. Brine is currently leaking from the injection tubing and flowing on to the ground. The brine scald area is 6 feet by 5 feet. Standing water within the scald area was tested with High Range Quantab. The Quantab was maxed out at over 6291 ppm Cl. The injection tubing has 40 psi with the tubing master valve closed. Identification is posted.**

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR **40**  Vac ANNULUSPRESSUR **202**  Vac FLOWMETER  Vac

HAULERNO: \_\_\_\_\_ LISCENSE\_NUM \_\_\_\_\_

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: **7/30/2020**

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued: **9/4/2019**

Required action to be completed by: **9/9/2019**

Reviewed by: \_\_\_\_\_

Extended action due: \_\_\_\_\_

Forward to: \_\_\_\_\_

Required action completed: \_\_\_\_\_

Duration: 2 hrs Section/Name \_\_\_\_\_