

API Well No.  
**34087204240000**

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER\_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1} 7** No. **7** WH\_LAT: **38.636890** WH\_LONG **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: \_\_\_\_\_ Phone \_\_\_\_\_

Address: \_\_\_\_\_

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification \_\_\_\_\_ Contact **JON SCOTT**

Inspection Comments:

**Compliance Notice # 1567619883 follow up inspection. Brine is currently leaking from the injection tubing and flowing on to the ground. The brine scald area is 8 feet 3 inches by 7 feet 6 inches. The scald area is extending South / Southwest of the well site. The scald area and brine are extending towards the wood line located 30 feet down slope. Standing water within the scald area was tested with High Range Quantabs in two locations. (1) 7 inches from the well casing, the Quantab was maxed out at over 6291 ppm Cl. (2) 4 feet from the well casing, the Quantab was maxed out at over 6291 ppm Cl. The injection tubing master valve is closed. Identification is posted. Pictures were taken verifying live stock presence at the well site.**

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSUR  Vac FLOWMETER  Vac

HAULERNO: \_\_\_\_\_ LISCENSE\_NUM \_\_\_\_\_

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: **8/7/2020**

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued: **9/4/2019**

Required action to be completed by: **9/9/2019**

Reviewed by: \_\_\_\_\_

Extended action due: \_\_\_\_\_

Forward to: \_\_\_\_\_

Required action completed: \_\_\_\_\_

Duration: 4.5 hrs Section/Name \_\_\_\_\_