

API Well No.  
**34087204240000**

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER\_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1} 7** No. **7** WH\_LAT: **38.636890** WH\_LONG: **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: \_\_\_\_\_ Phone \_\_\_\_\_

Address: \_\_\_\_\_

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification \_\_\_\_\_ Contact **JON SCOTT**

Inspection Comments:

**Compliance Notice # 1567619883 follow up inspection. The injection tubing master valve is closed. The injection tubing hole is open with no fluid leaking out. The annulus has 202 psi. Contaminated soil has not been removed. Identification is posted.**

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR **0**  Vac ANNULUSPRESSUR **202**  Vac FLOWMETER  Vac

HAULERNO: \_\_\_\_\_ LISCENSE\_NUM \_\_\_\_\_

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: **12/20/2019**

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued: **9/4/2019**

Required action to be completed by: **9/9/2019**

Reviewed by: \_\_\_\_\_

Extended action due:

Forward to: \_\_\_\_\_

Required action completed:

Duration: 1.5 hrs Section/Name \_\_\_\_\_