

API Well No.
34087204240000

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1}** 7 No. **7** WH_LAT: **38.636890** WH_LONG **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: _____ Phone _____

Address: _____

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification

Contact **JON SCOTT**

Inspection Comments:

Compliance Notice # 1567619883 follow up inspection. The injection tubing is currently leaking brine into the ground. The scald area is 48 inches by 36 inches with standing brine. The brine was tested on the ground with a high range Quantab. The Quantab was maxed out at over 6,000 ppm Cl. The injection tubing has 40 psi on it. The injection tubing master valve was closed and not opened during the inspection due to the over all poor condition of the tubing and fittings. Pictures were taken.

Accompanied by _____

INJECTIONPRESSUR **40** Vac ANNULUSPRESSUR **204** Vac FLOWMETER Vac

HAULERNO: _____ LISCENSE_NUM _____

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: **7/13/2020**

Signature: _____

Date notice of violation Issued: **9/4/2019**

JON SCOTT

Required action to be completed by: **9/9/2019**

Reviewed by: _____

Extended action due:

Forward to: _____

Required action completed:

Duration: 2.5 hrs

Section/Name

Jul 13, 2020 at 1:54:54 PM

