Ohio Deptartment of Natural Resources Divison of Mineral Resources Management

API Well No. Facility Report											
34155231960000		Project: SWIW-28-TRUM									
County: TRUMBULL	Twp. W/	ARREN	Sec:	0	Lot:	0	WI Typ:	SW_R			
Owner: PAC DEVELOPM			Resp Co	Same as	Operator						
Well Name: NATALE (SWIW #28)		No.:	1 WH_LAT:		0.000000 WH_LONG:			0.000000			
Directions to site:											
Inspection Type:	Salt Water Injection Well		Contact:		Phone						
Inspection Purpose:	Status Check		Addro	ess							
Type of Notification		Contact	RICK SKIDMO	ORE							

Inspection Comments:

I found the injection well not in use during my inspection. There were facility operators on location. I checked the murphy switch at the injection pump and found it set at 1,780 psi, which was well above the maximum allowable pressure of 1,070 psi. By having the automatic shut off switch set above the maximum allowable pressure, PAC Development LLC was in violation of the Ohio Administrative Code (OAC) 1501:9-3-07(G). The facility operator Inspection.CMMNT:

stated they have been shut down for a while due to the pressure. I left a message with Justin Caldwell for a return call concerning the issue. Also, I noticed two (2) frac tanks on location. According to the facility operator, PAC was prepping for future downhole work on the injection well. A follow up inspection will be conducted tomorrow

Accompanied by						
INJECTIONPRESSUR	SSUR Vac ANNULUSPRESSURE:		Vac	FLOWMETER:	Vac	
HAULERNO:	LIS	CENSE_NUM:				
LANDOWNERWAIVER:	P_REST_	PASS:	F_REST_PASS	6:		
Inspection Date:	3/2/2	2020	Sign	ature:		
Date notice of violation Issued:			0.9.1		RICK SKIDMORE	
Required action to be completed Extended action completed:	Revi	ewed by:				
Demoised action consoleted			Forw	ard to:		
Required action completed:			Dura	ition:	hrs	Section/Name