

API Well No.
34087204240000

Project: **ERP-1-LAWR**

County: **LAWRENCE** Twp **MASON** Sec: **20** Lot: **0** WI Typ: **ER_R**

Owner: **9619 PILLAR ENERGY LLC** Resp Co: **Same as Operator**

Well Name **EDWARD PINKERMAN {ERP#1} 7** No. **7** WH_LAT: **38.636890** WH_LONG: **-82.447060**

Directions to site: **Greasy Ridge Waterflood field**

Inspection Type: **Enhanced Recovery Project**

Contact: _____ Phone _____

Address: _____

Inspection Purpose: **Compliance Notice Follow-up.**

Type of Notification _____ Contact **JON SCOTT**

Inspection Comments:

Compliance Notice # 1567619883 follow up inspection. The injection line valve is closed. The injection tubing master valve is closed. The tubing leak has not been repaired. Contaminated soil has not been removed.

Accompanied by _____

INJECTIONPRESSUR **0** Vac ANNULUSPRESSUR **230** Vac FLOWMETER Vac

HAULERNO: _____ LISCENSE_NUM _____

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: **10/15/2019**

Signature: _____
JON SCOTT

Date notice of violation Issued: **9/4/2019**

Required action to be completed by: **9/9/2019**

Reviewed by: _____

Extended action due: _____

Forward to: _____

Required action completed: _____

Duration: 0.4 hrs Section/Name _____