

Ohio Department of Natural Resources  
Division of Mineral Resources Management

API Well No. 34155231960000 Facility Report  
Project: SWIW-28-TRUM  
County: TRUMBULL Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW\_R  
Owner: PAC DEVELOPMENT LLC Resp Co  
Well Name: NATALE (SWIW #28) No.: 1 WH\_LAT: 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone  
Inspection Purpose: Status Check Address  
Type of Notification Contact RICK SKIDMORE

Inspection Comments:

I was on location to inspect the UIC facility. I found the injection well pressure over the maximum allowable pressure by 30 psi. The soil and gravel around the injection well had oil residue. An identification sign is posted at the well and facility. I told the facility operator to immediately reduce the pressure. The facility operator stated the injection has been shut down due to the pressure and the area around the well impacted by the oil residue will be cleaned up. A follow-up inspection will be conducted by 1/18/2018.

Accompanied by  
INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 40 Vac FLOWMETER: Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER: P\_REST\_PASS: F\_REST\_PASS:

Inspection Date: 1/12/2018

Date notice of violation Issued: Signature: RICK SKIDMORE

Required action to be completed by: Reviewed by:

Extended action completed: Forward to:

Required action completed: Duration: hrs Section/Name