



# Ohio Department of Natural Resources

JOHN R. KASICH, GOVERNOR

JAMES ZEHRINGER, DIRECTOR

**Richard J. Simmers, Chief**  
**Division of Oil and Gas Resources Management**  
2045 Morse Road – Bldg. F-2  
Columbus, OH 43229-6693  
Phone: (614) 265-6922, Fax: (614) 265-6910

June 11, 2015

Michael DeWine  
Attorney General of Ohio  
Environmental Enforcement Section  
30 E. Broad Street, 25<sup>th</sup> Floor  
Columbus, Ohio 43215

**RE: Enforcement Referral for Adams Oil & Gas**

Dear Mr. DeWine:

I hereby request that you initiate civil and/or criminal proceedings under Chapter 1509 of the Ohio Revised Code, including all necessary legal and equitable actions, and seek appropriate relief, including penalties, against Adams Oil & Gas and any other appropriate persons for violations of Chapter 1509 of the Ohio Revised Code and rules adopted thereunder.

Megan De Lisi is the primary contact with regard to this referral. Please coordinate all negotiations and any resolution of this matter with Ms. De Lisi. She may be reached at 614-265-6937. Appropriate documentation to support this request is enclosed with this letter.

Thank you for your attention to this matter.

Sincerely,

*Jason R. Kell for*  
*Richard J. Simmers*

Richard J. Simmers, Chief  
Division of Oil and Gas Resources Management

cc: Dale Vitale, Attorney General's Office, EES Chief  
Dan Martin, Attorney General's Office, Supervising Attorney, EES/ODNR  
Michael Williams, Chief Legal Counsel, ODNR  
Robert Worstall, Deputy Chief, Division of Oil & Gas Resources Management  
Andrew Adgate, UIC Program Manager  
Eric Vendel, Legal Counsel, Division of Oil & Gas Resources Management



# Ohio Department of Natural Resources

JOHN R. KASICH, GOVERNOR

JAMES ZEHRINGER, DIRECTOR

*Richard J. Simmers, Chief*  
Division of Oil and Gas Resources Management  
2045 Morse Road, Building H-3  
Columbus, OH 43229-6693  
Phone: (614) 265-6633; Fax: (614) 265-7999

# 7851

## ORDER BY THE CHIEF

**TO: Adams Oil and Gas**  
**209 Bluebird Drive**  
**Washington, West Virginia 26181**

**ORDER NUMBER: 2011-50**

**DATE: December 21, 2011**

**RE: Permit No. 318**  
**Well No. 1**

**Lease: S. Austin; ERP No. 1**  
**County: Vinton**  
**Township: Berlin**

### **SUBJECT: PLUGGING REQUIRED**

The Chief of the Division of Oil and Gas Resources Management ("Division") having given due consideration to the matter contained herein makes the following Findings and issues the following Orders:

### **FINDINGS:**

- (1) Adams Oil and Gas is the owner of the above referenced injection well.
- (2) On December 5, 2011, an inspection revealed that the S. Austin #1 (ERP #1) well is incapable of injecting fluids and is in violation of Chapter 1501: 9-5-10 (J) of the Ohio Administrative Code and continues to be incapable of injection as of this date.


### **ORDERS:**

- (1) Adams Oil and Gas its successors, assignees, and agents shall do one of the following:
  - (A) Within ten (10) days receipt of this Order, place the referenced injection well into operation and completely comply to clean up, restore, and replace equipment on the S. Austin #1 injection surface facility.

- (B) Within thirty (30) days of receipt of this Order, **Adams Oil and Gas** shall apply for a plugging permit and cause the referenced well to be properly plugged and abandoned pursuant to Section 1509.12 of the Ohio Revised Code.

12.21.11

Issue Date



Richard J. Simmers, Chief

Division of Oil and Gas Resources Management

**APPEAL PROCEDURES:**

Addressee will be afforded an informal hearing, if requested, pursuant to Section 1509.06 of the Ohio Revised Code. If an informal hearing is desired, contact Richard J. Simmers, Chief, Division of Oil and Gas Resources Management, at (614) 265-6633. If you have any questions regarding this matter, please contact Tom Tomastik at (614) 265-1032.

Addressee is hereby notified that this action is final and effective and may be appealed to the Oil and Gas Commission pursuant to Section 1509.36 of the Ohio Revised Code. The appeal must be in writing and must set forth the orders complained of and the grounds upon which the appeal is based. Such appeal must be filed with the Oil and Gas Commission at the following address: Oil and Gas Commission, Linda Osterman, 2045 Morse Road, F-2, Columbus, Ohio 43229, within thirty (30) days after the receipt of this Order.

In addition, notice of the filing of the appeal must be filed with Richard J. Simmers; Chief of the Division of Oil and Gas Resources Management, Building H-2, 2045 Morse Road, Columbus, Ohio 43229-6693, within three (3) days after the appeal is filed with the Oil and Gas Commission. Any questions related to this Order should be directed to Tom Tomastik at (614) 265-1032.

JMB:tet/csc

Cc: Jon Scott, Mineral Resources Inspector  
Surety File  
Well File  
Legal File

CERTIFIED MAIL NO.: 91 7108 2133 3932 1019 1822

Ohio Department of Natural Resources  
Division of Oil & Gas Resources Management  
Facility Report

API Well No.

**34163203180000**

Project: **ERP-1-VINT**

County: **VINTON** Twp **SWAN** Sec: **25** Lot: **0** WI Typ: **EOR**

Owner **7851 ADAMS OIL & GAS** Resp Co

Well Name **S. AUSTIN {ERP#1}** 1 No. WH\_LAT **39.320530** WH\_LONG: **82.426160**

Directions to site:

Inspection Type: **Enhanced Recovery Project** Contact: Phone  
Inspection Purpose: **Order Follow-up** Address

Type of Notification Contact **JON SCOTT**

Inspection Comments:

**Chief's Order 2011-50 follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Well site is overgrown with vegetation. There has been recent activity near the well, the access road and an area near the unloading pad have been mowed recently. The containment dike is full of water with aquatic vegetation. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.**

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  0  Vac ANNULUSPRESSURE:  0  Vac FLOWMETER:  Vac

HAULERNO: LICENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: **6/10/2015**

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action due:

Forward to: \_\_\_\_\_

Required action completed:


Duration: \_\_\_\_\_ hrs Section/Name

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the unloading pad for the Adams Oil and Gas Enhanced Recovery Injection well 34-163-20318. Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This Photo shows the side of the facility pump house. All injection equipment has been removed.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This Photo shows the inside of the facility pump house.

Photo taken on 6-10-15 By ODNR/DOGGM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the 34-163-20318 Enhanced Recovery Injection Well. Note the injection tubing is not equipped with a master valve. The annulus has zero pressure. The well is not connected to injection lines or equipment.

Photo taken on 6-10-15 By ODNr/DOGRM UIC Inspector Jon Scott.



34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the state issued 1000 psi gauge installed on the annulus with all valves open. Annulus has zero pressure.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.


34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows another view of the state issued 1000 psi gauge installed on the annulus with all valves open. Annulus has zero pressure.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the containment dike wall. Note the aquatic vegetation in the containment dike.

Photo taken on 6-10-15 By ODNR/DOGGM UIC Inspector Jon Scott.

34-163-20318, Adams Oil and Gas, Enhanced Recovery Injection Well. Chief's Order 2011-50 Follow up inspection Photos.



This photo shows the Containment dike with the two 210 barrel tanks. The dike is full of water and aquatic vegetation.

Photo taken on 6-10-15 By ODNR/DOGRM UIC Inspector Jon Scott.

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.  
**34163203180000**

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Order Follow-up

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Site is overgrown with vegetation. There has been recent activity near the well, small trees have been cut down and branches are all around the well site. The containment dike is full of water with aquatic vegetation. There were no visible signs of the crude oil (in the containment dike) that was observed during the previous inspection. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.

Accompanied by \_\_\_\_\_  
INJECTIONPRESSUR 0  Vac ANNULSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 3/19/2015

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.  
34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Order Follow-up

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Site is overgrown with vegetation. Containment dike is full of water with aquatic vegetation and fish. A skim coating of oil is on 25% of the surface area of the water. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/24/2014

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed non-compliance. No action has been taken to resolve violations.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 6/11/2008

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 6/11/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Field Visit or Inspection Contact ANDREW THOMAS

Inspection Comments:

Accompanied Inspector Jon Scott on this inspection. No attempts have been made by company to gain compliance. Well head is disconnected from lines. Annulus and injection pressures are 0. Containment dike is full of water. Spoke with the caretakers of the property, and gave them my card to give to the land owner.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 1/15/2013

Signature: \_\_\_\_\_  
ANDREW THOMAS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed compliance. Identification is displayed at the well and the storage tanks. However, the identification does not contain a lease name and Mountaineer Gas Transmission is listed as the owner. At the time of the inspection, RBDMS showed that Adams Oil & Gas is still the owner of this well. The previous inspection (mini-test) showed positive pressure on the annulus. During the inspection, a ball valve could not be opened therefore, the pressure was not obtained.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LICENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 12/23/2008

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 12/23/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed non-compliance. No action has been taken to resolve the violations. Mr. Jamie Adams states that the well ownership issue has not been resolved. Also stating that they have not been working around the Vinton County area because of this issue.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/5/2007

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 7/5/2007

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

CN follow up. Injection well is disconnected from injection lines. No pump on site. Tank dike is full of water. Well is not capable of injection. No change from last inspection.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 8  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/27/2011

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed identification has now been corrected at the well. No injection at this time. The motor and injection lines from inside the shed have been removed.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 3  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 1/5/2011

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.  
34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: Lot: WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Follow-up on NOV, Non-Compliance, well still idle and incapable of producing.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 11/17/2004

Signature: \_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LA1

0.000000 WH\_LONG:

0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:

Phone

Inspection Purpose: NOV Follow-up

Address

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Follow-up on NOV, Non-Compliance, well still idle.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

8/16/2004

Signature:

DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact: BRENT BEAR

Inspection Comments:

A mini-test revealed 3 psi loss after 15 minutes. The well passed the required test.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 297  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 11/12/2008

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 11/12/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Order Follow-up

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Brent Bear will issue NOV.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LICENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/19/2006

Signature: \_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 7/19/2006

Duration: \_\_\_\_\_ hrs Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Field Visit or Inspection Contact ANDREW THOMAS

Inspection Comments:

No change since last inspection. Accompanied by inspector Morgan Button.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LICENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 8/2/2012

Signature:

Date notice of violation Issued:

ANDREW THOMAS

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LA1

0.000000 WH\_LONG:

0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:

Phone

Inspection Purpose: Order Follow-up

Address

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Well is idle, unable to locate company, may need to turn over to I & O section for plugging.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

1/29/2004

Signature:

DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection was conducted with Mr. Jeff Fry, West Region Oil & Gas Supervisor and UIC Field Supervisor. It was noted that the well status remains the same.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/1/2009

Signature: \_\_\_\_\_

Date notice of violation Issued:

BRENT BEAR

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed positive pressure on the annular side of the well. As previously noted, the well status remains the same. The observed identification at tanks and well is not complete and the surface facility not connected for injection.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 7  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 12/11/2009

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed non-compliance. The well status remains unchanged since the last inspection. No injection at this time. The dike contains fresh water and the fluid level will need to be addressed for capacity. The identification sign at well and storage tank location remains incomplete.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 2  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 3/15/2010

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LAT

0.000000 WH\_LONG:

0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:

Phone

Inspection Purpose: NOMSV Follow-up

Address

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Follow-up on Chief's Order, Non-Compliance, well still idle and not injecting at this time, hung a copy of the Chief's Order on the well and storage tanks.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

5/8/2003

Signature:

\_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: Lot: WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact DAN GOINS

Inspection Comments:

Follow - up on NOV , Non - Compliance, no action to replace valve , rewrite ID at tanks , or make well capable of injecting.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 10/31/2001

Signature: \_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LA1

0.000000 WH\_LONG:

0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:

Phone

Inspection Purpose: Enforcement Action Follow-up

Address

Type of Notification

Contact DAN GOINS

Inspection Comments:

Follow-up on NOV, Non-Compliance, no action to comply with NOV or Chief's Order. Also dike standing full of fresh water at this time.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

2/6/2002

Signature:

DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LAT

0.000000 WH\_LONG:

0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:  
Address

Phone

Inspection Purpose: NOMSV Follow-up

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

Follow - up on Chief's Order, well still idle and incapable of injecting brine. No action seen to comply with NOV or Chief's Order.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

7/28/2003

Signature:

\_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact JON SCOTT

Inspection Comments:

Follow up inspection for Compliance notice No. 1556115216 issued 4-6-2011. Annulus has zero pressure. Well is disconnected from injection lines. No pump equipment is on location. Dike is full of water. Identification is upside down on ground at well head. Well is not capable of injection. Photos were taken during inspection.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 12/5/2011

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Order Follow-up

Type of Notification Contact JON SCOTT

Inspection Comments:

Enhanced recovery injection well is not connected to injection lines or equipment. Annulus has zero pressure. Injection tubing has zero pressure. Tank dike is full of water. Photos were taken of enhanced recovery injection well, tanks and dike.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 1/20/2012

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Order Follow-up

Type of Notification Contact JON SCOTT

Inspection Comments:

Enhanced recovery injection well is not connected to injection lines or equipment. Annulus has zero pressure. Injection tubing has zero pressure. Tank dike is full of water. Photos were taken of enhanced recovery injection well, tanks and dike.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 2/7/2012

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed non-compliance. No action has been taken to resolve violations. Request Chiefs Order.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/29/2008

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 7/29/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection was conducted on 9/13/2006. During the inspection, it was noted that the previously noted violations have not been resolved. The company was contacted by telephone on 9/13/2006 and informed that the violations still exist.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/13/2006

Signature: \_\_\_\_\_

Date notice of violation Issued:

BRENT BEAR

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 9/13/2006

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed that the identification has been corrected. The well status remains the same. No injection at this time.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 2  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/8/2010

Signature: \_\_\_\_\_

Date notice of violation Issued:

BRENT BEAR

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOV Follow-up

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed that violations have not been resolved. No action has been taken to bring the EOR well into compliance. The injection side of the well does not contain 1/4 inch fitting which would allow placement of gauge. Annulus side of the well does not contain pressure. A mini-test is required. No identification observed. Dike is full and needs pumped.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 11/5/2007

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 11/5/2007

Duration: \_\_\_\_\_ hrs Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Enhanced recovery injection well is not connected to injection lines or equipment. Annulus has zero pressure. Injection tubing has zero pressure. Tank dike is full of water. Photos were taken of enhanced recovery injection well, tanks and dike. Accompanied by Andy Thomas MRI 2.  
Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 1/15/2013

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Injection tubing is open with no valve. Dike is full of water and vegetation. Annulus has zero pressure. Identification is on the ground. The access road to the well has been mowed. There has been no efforts made to equip the well for injection. Accompanied by Inspector Kip Thompson.  
Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/12/2013

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Site is overgrown with vegetation. Containment dike is full of water with aquatic vegetation and fish. A skim coating of oil is on 25% of the surface area of the water. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/24/2014

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Injection tubing is open with no master valve. Dike is full of water and vegetation. Annulus has zero pressure. No identification. There has been no efforts made to equip the well for injection. (no injection lines or injection filters, pumps).

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 5/13/2014

Signature: \_\_\_\_\_

Date notice of violation Issued:

JON SCOTT

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Site is overgrown with vegetation. Containment dike is full of water with aquatic vegetation and fish. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.

Accompanied by

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/3/2014

Signature: \_\_\_\_\_

Date notice of violation Issued:

JON SCOTT

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow up inspection. Inspected the containment dike, tanks, unloading pad, annulus pressure and injection pressure. The injection tubing is open with no master valve. Annulus has zero pressure. Site is overgrown with vegetation. There has been recent activity near the well, small trees have been cut down and branches are all around the well site. The containment dike is full of water with aquatic vegetation. There were no visible signs of the crude oil (in the containment dike) that was observed during the previous inspection. The well is not connected to injection equipment and is not capable of injection. No identification is posted on the location.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 3/19/2015

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: Lot: WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT WH\_LONG:

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: NOMSV Follow-up

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

An inspection of the well revealed that the well is idle and incapable of injecting brine at this time, MIT test has not been done, production lines and pump not hooked up to well. No ID at the well or tanks.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 11/25/2002

Signature: DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed that a 1/4" valve has been placed on the injection side of the well. The valve for the annulus has been repaired and will now open. No pressure was observed on the annulus and injection side of the well. At the time of the inspection, the dike still contained fluid with no observed leaks. A section along the side of this dike contains a trench and will need to be repaired. The company has been instructed of this deficiency to include the liner that contains small tears along the top. The identification at both the well and tank battery locations have been painted over incorrect well owner, Mountaineer Gas Transmission. Adams Oil & Gas and ERP # will need to be added to the ID.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 4/7/2009

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone  
Address

Inspection Purpose: Status Check

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed that the status remains unchanged. No injection at this time. The tanks are not connected to the well and valves are closed. The pump does not contain a belt. 2" black plastic from 210 bbl tank to pump (inlet) and 2" steel from pump to well (outlet) found disconnected at well. ID found not incomplete as, well owner name, emergency#, well name and ERP# were not observed. 6" of freshwater with aquatic life observed in dike. A 1' x 6" trench cut out along backside of dike for drainage. (2) 210 bbl tanks are corroding, but unable to tell if leaking due to fluid inside dike. The ID at tank location contains only correct owner name and emergency contact#.. The dike height is from 6' to 7'. The liner contains approximately 5 tears along the top backside of dike. The tears range from 6" to 2'. Positive pressure was observed on annulus.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 2  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 6/12/2009

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.  
34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: Lot: WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact DAN GOINS

Inspection Comments:

Follow - up on NOV , Non - Complainece , company has not put ID at well and or storage tanks , and put a 1/4" valve on the well for inspection.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 3/22/2001

Signature: DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Injection tubing is open with no valve. Dike is full of water and vegetation. Annulus has zero pressure. Identification is on the ground. There has been no efforts made to equip the well for injection.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 11/19/2013

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed non-compliance.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 2/25/2008

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 2/25/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Field Visit or Inspection Contact ANDREW THOMAS

Inspection Comments:

Accompanied Inspector Jon Scott on an inspection of this well and tank battery. Updated photos were taken.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 2/7/2012

Signature: ANDREW THOMAS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 2/7/2012

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

A follow-up inspection revealed non-compliance. No action has been taken to resolve violations. The injection side of the well will require a 1/4" fitting that will allow for a gauge to be installed. The valve was opened and no vacuum or pressure was observed. At the time of this inspection, a valve located on the annular side of the well could not be opened. Therefore, the pressure was not obtained. The meter connected to this well has been removed. No identification was observed at the well and storage tanks. A trench cut in the side of the dike will need to be repaired. The liner contains small tears at locations along the top of the dike.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/11/2008

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 9/11/2008

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact BRENT BEAR

Inspection Comments:

An inspection revealed that the injection side of the well will need to be equipped with a 1/4" valve. The annulus pressure was not obtained, due to a valve that was stuck. The dike is full of fluid and will need to be pumped. The identification still shows the wrong owner. The well owner has been instructed to correct deficiencies.  
Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 3/3/2009

Signature: BRENT BEAR

Date notice of violation Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow-up inspection. Wellhead has been turned 3/4 of a turn. Injection tubing master valve and cross with two valves has been removed from the well. Annulus pressure gauge is damaged. Identification is on the ground at the well. There was no pressure on the annulus. Injection tubing is open with no valve. Containment dike is full of water. Site is over grown with vegetation. There are two steel tanks in the dike. Photos were taken.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR 0  Vac ANNULUSPRESSURE: 0  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 7/17/2013

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name



Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LA1 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Enhanced Recovery Project Contact: Phone

Inspection Purpose: Order Follow-up Address

Type of Notification Contact JON SCOTT

Inspection Comments:

Chief's Order follow-up inspection. There has been no changes to the well or surface facility since the last inspection. Wellhead has been turned 3/4 of a turn. Injection tubing master valve and cross with two valves has been removed from the well. Annulus pressure gauge is damaged. Identification is on the ground at the well. There was no pressure on the annulus. Injection tubing is open with no valve. Containment dike is full of water. Site is over grown with vegetation. There are two steel tanks in the dike. Photos were taken.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 8/12/2013

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 39.320520 WH\_LONG: -82.426050

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone  
Address

Inspection Purpose: Status Check

Type of Notification Field Visit or Inspection Contact ANDREW THOMAS

Inspection Comments:

Upon arrival it was noted by myself and Rob Stonerock that there was no pump equipment in the building adjacent to the tank battery. As we walked up to the tank battery, we noted several rips in the liner. There is a pipe that sticks out toward the building that has been cut. Containment area is filled with water up to about 1 foot from the top of the dike. Proper identification was noted on the well head. There are no lines going to/from well head to tank battery.

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 2/10/2011

Signature: \_\_\_\_\_  
ANDREW THOMAS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 39.320630 WH\_LONG: -82.426290

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact KIP THOMPSON

Inspection Comments:

Compliance notice follow-up. The well consists of 2-210 barrel tanks, injection well and 3- 100 barrel tanks. Nothing has been done to bring the well into compliance.

Inspection.CMMNT:

Accompanied by

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 4/7/2014

Signature: \_\_\_\_\_  
KIP THOMPSON

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON Twp. SWAN Sec: 0 Lot: 0 WI Typ: EOR

Owner: ADAMS OIL & GAS Resp Co

Well Name: GRIM ORA No.: 1 WH\_LAT 0.000000 WH\_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact KIP THOMPSON

Inspection Comments:

I accompanied Jon Scott on the inspection of this well. There is a Chiefs order that has not be satisfied. The well is idle and in disrepair. The dike has 18" of water in it. There was no pressure on the annulus.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR  Vac ANNULUSPRESSURE:  Vac FLOWMETER:  Vac

HAULERNO: LISCENSE\_NUM:

LANDOWNERWAIVER:  P\_REST\_PASS:  F\_REST\_PASS:

Inspection Date: 9/12/2013

Signature: \_\_\_\_\_

Date notice of violation Issued:

KIP THOMPSON

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs Section/Name

Ohio Department of Natural Resources  
Division of Mineral Resources Management  
Facility Report

API Well No.

34163203180000

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec:

Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

WH\_LAT

39.320590 WH\_LONG:

-82.426120

Directions to site:

Inspection Type: Orphan

Contact:

Phone

Inspection Purpose: Request

Address

Type of Notification Field Visit or Inspection Contact DAN GOINS

Inspection Comments:

An inspection of the well revealed well is incapable of producing, will start a I & O file on well.

Inspection.CMMNT:

Accompanied by \_\_\_\_\_

INJECTIONPRESSUR

Vac

ANNULUSPRESSURE:

Vac

FLOWMETER:

Vac

HAULERNO:

LISCENSE\_NUM:

LANDOWNERWAIVER:

P\_REST\_PASS:

F\_REST\_PASS:

Inspection Date:

4/12/2004

Signature:

\_\_\_\_\_  
DAN GOINS

Date notice of violation Issued:

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed:

Duration: \_\_\_\_\_ hrs

Section/Name

# Compliance Action

No 379016273

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 286-6411

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:  
Address

Phone

Inspection Purpose: Status Check

Type of Notification

Contact JON SCOTT

NOV Requirements: Inspection requires action

FOLLOW UP TO NOV # 1340532399 FOLLOW UP TO NOV # 1556115216 Injection well is disconnected from injection lines. No pump equipment on site. Tank dike is full of water. Remove water from dike. Annulus has zero pressure. Annulus must be tested to maximum injection pressure of 562 psi for 15 minutes with no more than 5% loss. Well in not capable of injection. Well must be capable of injection or plugged 1509-22 (J). Schedule mechanical integrity test with Inspector Jon Scott 740-624-4963.

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by \_\_\_\_\_

INJECTION/PRESSURE

0  Vac

ANNULUS/PRESSURE:

0  Vac

FLOW/METER

Vac

HAULER NO

LISCENSE\_NUM:

Inspection Date: 3/31/2011

Signature:

Date notice of violation Issued: 4/6/2011

JON SCOTT

Required action to be completed by: 5/6/2011

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 2/7/2012

Section/Name

# Compliance Action

No 745432480

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 286-6411

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: \_\_\_\_\_  
Address Phone

Inspection Purpose: Status Check

Type of Notification Contact JON SCOTT

NOV Requirements: Inspection requires action

FOLLOW UP TO NOV # 1556115216 Injection well is disconnected from injection lines. No pump equipment on site. Tank dike is full of water. Remove water from dike. Annulus has zero pressure. Annulus must be tested to maximum injection pressure of 562 psi for 15 minutes with no more than 5% loss. Well in not capable of injection. Well must be capable of injection or plugged 1509-22 (J). Schedule mechanical integrity test with Inspector Jon Scott 740-624-4963.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDTIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by \_\_\_\_\_

INJECTION/PRESSURE 0  Vac ANNULUS/PRESSURE: 0  Vac FLOW/METER  Vac

HAULER NO LICENSE\_NUM:

Inspection Date: 3/31/2011

Signature: \_\_\_\_\_  
JON SCOTT

Date notice of violation Issued: 4/6/2011

Required action to be completed by: 5/6/2011

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 2/7/2012

Section/Name

# Compliance Action

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 286-6411

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose: Status Check

Type of Notification Contact JON SCOTT

1509: 03	1501: 9-5-10(F)	Failure to monitor annulus pressure
1509: 12	1501: 9-5-10(J)	Well incapable of inj./production
1509: 23	1501: 9-9-05(A)9	No SPCC dike/or failure to keep dike free of water or oil

NOV Requirements: Inspection requires action

Injection well is disconnected from injection lines. No pump equipment on site. Tank dike is full of water. Remove water from dike. Annulus has zero pressure. Annulus must be tested to maximum injection pressure of 562 psi for 15 minutes with no more than 5% loss. Well in not capable of injection. Well must be capable of injection or plugged 1509-22 (J). Schedule mechanical integrity test with Inspector Jon Scott 740-624-4963.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by \_\_\_\_\_

INJECTION/PRESSURE 0  Vac ANNULUS/PRESSURE: 0  Vac FLOW/METER  Vac

HAULER NO LISCENSE\_NUM:

Inspection Date: 3/31/2011

Signature: JON SCOTT

Date notice of violation Issued: 4/6/2011

Required action to be completed by: 5/6/2011

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 2/7/2012

Section/Name



# Compliance Action

No 1340532399

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 286-6411

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:  
Address

Phone

Inspection Purpose: Status Check

Type of Notification

Contact JON SCOTT

NOV Requirements: Inspection requires action

FOLLOW UP TO NOV # 1556115216 Injection well is disconnected from injection lines. No pump equipment on site. Tank dike is full of water. Remove water from dike. Annulus has zero pressure. Annulus must be tested to maximum injection pressure of 562 psi for 15 minutes with no more than 5% loss. Well in not capable of injection. Well must be capable of injection or plugged 1509-22 (J). Schedule mechanical integrity test with Inspector Jon Scott 740-624-4963.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE 0  Vac ANNULUS/PRESSURE: 0  Vac FLOW/METER  Vac

HAULER NO

LISCENSE\_NUM:

Inspection Date: 3/31/2011

Signature:

Date notice of violation Issued: 4/6/2011

JON SCOTT

Required action to be completed by: 5/6/2011

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 2/7/2012

Section/Name

# Notice of Violation

No 1213795798

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management  
Region Phone (740) 392-4499

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twsp: SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: \_\_\_\_\_  
Address Phone

Inspection Purpose: Status Check

Type of Notification Notice of Violation Contact BRENT BEAR

1509: 03	1501: 9-5-10(J)	Failure to plug
1509: 23	1501: NONE(H)	Insufficient/No identification

NOV Requirements: Inspection requires action

An inspection revealed that Adams Oil & Gas has failed to comply with previously noted violations. Positive pressure is still needed on the annulus side of the well. A mini-test has not been performed and will be required. The unloading pad needs repaired, due to the concrete that is cracking. No identification was observed at the well and storage tanks. A new NOV will be reissued to the company. A Notice of Violation had been issued on 8/10/2006 requiring a mini-test be performed on this ERP, due to no pressure on annulus. Also noted was that identification was needed at the storage tanks and location on or near the wellhead. The unloading pad

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by \_\_\_\_\_

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO \_\_\_\_\_ LICENSE\_NUM: \_\_\_\_\_

Inspection Date: 6/11/2008

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued: 6/25/2008

Required action to be completed by: 7/25/2008

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 11/12/2008

Section/Name

# Notice of Violation

No -1228523624

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 588-0631

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose: Request

Type of Notification Notice of Violation Contact DAN GOINS

**1509: 12 1501: 9-5-10(J) Well incapable of inj./production**

NOV Requirements: Inspection requires action

FOLLOW UP TO NOV # 1085405554 Reviewing records at the Vinton Co Courthouse, show the well has been assigned to Team RM, Inc., 2178 Castle Crest Dr., Worthington, Ohio NEED TO PLUG OR PUT WELL INTO PRODUCTION(INJECTING), MUST PASS A MIT TEST. FAILURE TO COMPLY MAY RESULT IN A FORFEITURE OF BOND.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO LISCENSE\_NUM:

Inspection Date: 5/24/2004

Signature: DAN GOINS

Date notice of violation Issued: 5/24/2004

Required action to be completed by: 6/28/2004

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 4/14/2006

Section/Name

# Notice of Violation

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 588-0631

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp: SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: \_\_\_\_\_  
Address Phone

Inspection Purpose:

Type of Notification Contact DAN GOINS

NOV Requirements: Inspection requires action

1501:9-5-09 (A)(3) AND 1501:9-9-05 (A)(10)

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE 0  Vac ANNULUS/PRESSURE: 0  Vac FLOW/METER 0  Vac

HAULER NO LISCENSE\_NUM:

Inspection Date: 2/15/2001

Signature: \_\_\_\_\_  
DAN GOINS

Date notice of violation Issued: 2/15/2001

Required action to be completed by:

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 2/7/2012

Section/Name

# Notice of Violation

No UIC329

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management  
Region Phone

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co 1728

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose:

Type of Notification Contact

NOV Requirements: Inspection requires action

ACTION CH.ORD 1501:9-3-07 (E)(F) DELINQUENT QTLY RPT.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO LICENSE\_NUM:

Inspection Date: 3/13/1987

Signature: \_\_\_\_\_

Date notice of violation Issued: 3/13/1987

Required action to be completed by: 3/23/1987

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 4/13/1998

Section/Name

# Notice of Violation

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management  
Region Phone (740) 588-0631

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose: Request

Type of Notification Notice of Violation Contact DAN GOINS

1509: 12	1501: 9-5-10(J)	Well incapable of inj./production
----------	-----------------	-----------------------------------

NOV Requirements: Inspection requires action

Reviewing records at the Vinton Co Courthouse, show the well has been assigned to Team RM, Inc., 2178 Castle Crest Dr., Worthington, Ohio NEED TO PLUG OR PUT WELL INTO PRODUCTION(INJECTING), MUST PASS A MIT TEST. FAILURE TO COMPLY MAY RESULT IN A FORFEITURE OF BOND.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO LISCENSE\_NUM:

Inspection Date: 5/24/2004

Signature:

Date notice of violation Issued: 5/24/2004

DAN GOINS

Required action to be completed by: 6/28/2004

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 4/14/2006

Section/Name

# Notice of Violation

No 1154308579

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone (740) 392-4499

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp: SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: \_\_\_\_\_  
Address Phone

Inspection Purpose: Status Check

Type of Notification Notice of Violation Contact BRENT BEAR

1509: 03	1501: 9-5-10(F)	Failure to monitor annulus pressure
1509: 23	1501: NONE(H)	Insufficient/No identification
1509: 22[C]	1501: NONE(B)	Dike or pit not able to prevent escape of brine or other wastes
1509: 03	1501: 9-3-05[C]	Failure to pass required test

NOV Requirements: Inspection requires action

An inspection was conducted at the facility owned by Adams Oil & Gas on 7/19/2006. During the inspection, it was noted that there was no pressure at the injection or annulus side of the well. A mini test will be required. The dike needs repaired. The unloading pad also needs to be repaired because, it is cracking. No identification at the wellhead or at the storage tanks. It is recommended that the annulus side of the well be pressurized and a mini test be performed on the packer. The dike and the unloading pad must also be repaired and ID provided. Please provide identification at the well and storage tanks.

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by \_\_\_\_\_

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO \_\_\_\_\_ LISCENSE\_NUM: \_\_\_\_\_

Inspection Date: 7/19/2006

Signature: \_\_\_\_\_  
BRENT BEAR

Date notice of violation Issued: 8/10/2006

Reviewed by: \_\_\_\_\_

Required action to be completed by: 9/10/2006

Forward to: \_\_\_\_\_

Extended action completed:

Required action completed: 6/11/2008

Section/Name

# Notice of Violation

No UIC993

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co 1728

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact:  
Address

Phone

Inspection Purpose:

Type of Notification

Contact

NOV Requirements: Inspection requires action

ACTION CH.ORD 1501:9-3-07 E MONTHLY VOLUMES -TL

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE

Vac

ANNULUS/PRESSURE:

Vac

FLOW/METER

Vac

HAULER NO

LISCENSE\_NUM:

Inspection Date: 10/12/1990

Signature:

Date notice of violation Issued: 10/12/1990

Required action to be completed by: 10/18/1990

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 4/13/1998

Section/Name



# Notice of Violation

No UIC994

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management

Region Phone

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co 1728

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose:

Type of Notification Contact

NOV Requirements: Inspection requires action

ACTION CH.ORD 1501:9-3-07 F MONITOR ANNULAR -TL

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO LISCENSE\_NUM:

Inspection Date: 10/12/1990

Signature: \_\_\_\_\_

Date notice of violation Issued: 10/12/1990

Required action to be completed by: 10/18/1990

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 4/13/1998

Section/Name

# Notice of Violation

No UIC705

Ohio Department of Natural Resources  
Division of Oil and Gas Resources Management  
Region Phone

THIS IS TO NOTIFY YOU THAT AN INSPECTION WAS CONDUCTED BY THE ENFORCEMENT SECTION OF THE DIVISION OF OIL AND GAS RESOURCES MANAGEMENT, OHIO DEPARTMENT OF NATURAL RESOURCES, ON THE BELOW DATE, AND THE FOLLOWING VIOLATIONS WERE NOTED.

API Well No.

**34-163-20318-00-00**

Project: ERP-1-VINT

County: VINTON

Twp. SWAN

Sec: 25 Lot:

WI Typ: EOR

Owner: ADAMS OIL & GAS

Resp Co 1728

Well Name: GRIM ORA

No.: 1

Directions to site:

Inspection Type: Enhanced Recovery Project

Contact: Phone  
Address

Inspection Purpose:

Type of Notification Contact

NOV Requirements: Inspection requires action

ACTION CH.ORD 1501:9-5-10 (E) Delinquent Qtly Rpt.

Inspection.CMMNT:

OHIO REVISED CODE CHAPTER 1509. PROVIDES FOR ADDITIONAL NON-EXCLUSIVE REMEDIES WHICH THE DIVISION MAY PURSUE.

Accompanied by

INJECTION/PRESSURE  Vac ANNULUS/PRESSURE:  Vac FLOW/METER  Vac

HAULER NO LICENSE\_NUM:

Inspection Date: 6/13/1989

Signature: \_\_\_\_\_

Date notice of violation Issued: 6/13/1989

Required action to be completed by: 6/27/1989

Reviewed by: \_\_\_\_\_

Extended action completed:

Forward to: \_\_\_\_\_

Required action completed: 4/13/1998

Section/Name